

Radiatta Pine Plywood



Grading:

A Grade - Synthetic repairs are accepted up to 6. Boat type wood patches permitted up to 6. Small, wood-based putty repairs are allowed.

B Grade - Synthetic repairs are accepted up to 8. Boat type wood patches permitted up to 6. Small, wood-based putty repairs are allowed.

C Grade - Occasional tight knots up to 25mm wide are accepted.

Product Attributes:

- Phenolic Glue
- Radiatta Pine Grain does not telegraph
- Very tight edges
- +/-, 4mm (1/64) thickness tolerance
- TECO certified PS1-07-STANDARDS
- Well sanded, no torn grain
- Stays flat
- Cuts easily without splintering
- Very few core voids and splice gaps
- Uniform color

See special pricing on page 2:

Maywood, IL
1401 St. Charles Rd.
Maywood, IL 60153
P: 708.343.1515
F: 708.343.1616

Rockford, IL
1931 Eleventh St.
Rockford, IL 61104
P: 815.968.0921
F: 815.968.4720

Indianapolis, IN
6350 Brookville Rd.
Indianapolis, IN 46219
P: 317.353.6281
F: 317.356.3503

White Bear Lake, MN
4250 Otter Lake Rd.
White Bear Lake, MN 55110
P: 651.407.2800
F: 651.407.2801

Horn Lumber
4700 West 19th St.
Cicero, IL 60804
P: 773.847.7397
F: 773.847.7798

Special Radiatta Pine August Pricing:

AC Special

Code	Item Description	Plies	Unit Size	Per Piece	1 Unit	2+ Units
02-14-800	12mm 4x8 AC	5	80	\$78.78	\$74.10	\$70.00
02-22-800	18mm 4x8 AC	7	54	\$80.50	\$76.90	\$73.00

BC Special

Code	Item Description	Plies	Unit Size	Per Piece	1 Unit	2+ Units
02-22-806	18mm 4x8 BC	7	54	\$79.50	\$75.90	\$72.00

Special pricing now through August 31, 2021

Maywood, IL
1401 St. Charles Rd.
Maywood, IL 60153
P: 708.343.1515
F: 708.343.1616

Rockford, IL
1931 Eleventh St.
Rockford, IL 61104
P: 815.968.0921
F: 815.968.4720

Indianapolis, IN
6350 Brookville Rd.
Indianapolis, IN 46219
P: 317.353.6281
F: 317.356.3503

White Bear Lake, MN
4250 Otter Lake Rd.
White Bear Lake, MN 55110
P: 651.407.2800
F: 651.407.2801

Horn Lumber
4700 West 19th St.
Cicero, IL 60804
P: 773.847.7397
F: 773.847.7798